




Topographic map



Satellite imagery



Photographs of the Sackett Site, Priest Lake, Idaho, May 3, 2007



View looking south of fill material being placed on site.



View looking south along western edge of property - filled area, excavated wetland area, existing wetland (left to right)



View looking north along western edge of property - filled area, excavated wetland area, existing wetland (right to left)



View looking north along eastern edge of property - filled area, excavated wetland area, existing wetland (left to right)



View looking north from southern edge of property